

- 5-6 Seconds
- Accuracy to ±0.9°F
- Adjustable Calibration IP65 Water Resistant

Specifications

- NSF Approved
- On/Off Switch
- °C/°F Switchable
 -40 to 302°F Range

Measuring Range	
Accuracy	±0.9°F (±0.5°C) between 14 to 212°F (-10 to 100°C),
Display Resolution	
Auto Off	
Response Time	Approx. 6 seconds from ambient to 32°F
Display Size	0.47 H x 1.02 W inches (12 H x 26 W mm)
Water Resistance	IP65
Digit Size	0.39 H x 0.16 W inches (10 H x 4 W mm)
Probe Size	4.8 L x 0.1 dia. inches; reduces to 0.67 L x 0.06 (1/16") dia. inches
Minimum Immersion	Approx. 0.25 inch (6.4 mm)
Battery	3 volt, type CR2032 or equivalent x 1 piece (included);
	5,000 hours continuous operation
Product Size	1.3 H x 1.9 W x 1.1 D inches
	(35 H x 49 W x 28 D mm), excluding probe
Operating Range	32 to 122°F (0 to 50°C)

Instrument Operation Press the ⁽¹⁾ button to activate the thermometer. The unit will turn off automatically after 1 hour to save battery life.

Insert the stainless steel probe to the desired depth. The measured temperature will be shown on the LCD display within 5 to 6 seconds.

To Select °F or °C

Press the °C/°F button to select the desired temperature unit

Battery Installation

Replace the battery when low battery symbol 'Bat' flashes. Replace with a 3 volt, type CR2032 button cell battery or equivalent Use a screwdriver of suitable size to open the battery cover on the b Carefully remove battery with small flathead screwdriver. Install the new battery observing the correct polarity. Close the battery cover.

Calibration

- Remove the Phillips head screw on the front panel.
 Place the probe in a 32°F (0°C) temperature calibrator and let the reading become stable
- stable.
 3. Place a suitable size flathead screwdriver onto the screw hole and adjust the potentiometer to display 32°F (0°C).
 4. Place the probe in a 212°F (100°C) temperature calibrator and let the reading become stable.
 5. If needed, adjust the potentiorneter to display 212°F (100°C).
 6. Repeat step 2 to verify the 32°F (0°C) reading is within tolerance.
 7. Replace the Phillips head screw.

Care and Cleaning Clean the probe immediately after each measurement to avoid cross contamination. Do not expose the entire thermometer to temperatures below $32^{\circ}F$ (0°C) or over $122^{\circ}F$ (50°C). Incorrect readings or damage to the thermometer may result. Tighten the calibration and battery compartment screws firmly to maintain the unit's water resistance. Do not leave inside ovens. Not submersible.

Technical Support For warranty, service, and technical assistance, please contact ThermoWorks' Technical Support at **(801) 756-7705** or email at techsupport@thermoworks.com.

For additional cooking tips and doneness temperatures, and to see the full line of ThermoWorks tools, visit our website at www.thermoworks.com.

Made in Chin (६ 🕅

ThermoWorks, Inc. Utah, U.S.A. Ph: 801-756-7705 Fax: 801-756-8948 www.thermoworks.com P-10-001-01-1

f y B 🖮 🖸 Ø RT301WA - Super-Fast Pocket Thermometer 18122 27125